


Originalbetriebsanleitung

XXXLutz KG,
Römerstrasse 39,
4600 Wels, Austria

14810007/01 POLLA




× 2





30mins



A x 1	B x 7	C x 2	D x 12	E x 18	F x 2	G x 3	H x 4
							
H117mm	H120mm	φ 30x 140 mm	M8x20mm	M8x30mm	M5	233x3x35mm	φ 22mm
I x 2	J x 2	K x 8	L x 1	M x 1			
							
70x49x13mm	65x44x13mm	M6 x 25mm	M8 x 50mm	M4			

1



2

A x 1



H117mm

B x 5



H120mm

E x 10




M8x30mm

F x 2



M5



3

I x 2



70x49x13mm

J x 2



65x44x13mm

K x 8




M6 x 25mm


M x 1



M4




4




5

 Bx2	 Ex8	 Hx4
 Cx2	 Fx1	 Lx1
 Dx12	 Gx3	



6




7

D x 12



M8x20mm

G x 3




233x3x35mm

F x 1



M5



8

E x 4



M8x30mm

H x 4




233x3x35mm

F x 1



M5



9

B x 2



H120mm

C x 2



φ 30x 140 mm

E x 4




M8x30mm


F x 1




M5



10



11




12


L x 1




M8 x 50mm




13




14




15




16




17



18



17



18

