


05180032/03








2PER



45 MIN

PART LIST







HARDWARE LIST

A X14 	B X14 	C X34 DIA8x30mm	D X10 DIA3x30mm	E X4
F X8 DIA4x20mm	G X4 DIA6x60mm	H X4 	I X4 	J X4 DIA6x5mm
K X1 	L X41 DIA3x14mm	M X4 	N X4 	O X8
P X1 DIA3x50mm	Q X1 	R X1 	S X8 	T X14
U X4 DIA3x25mm	V X4 			

STEP 1



STEP 2




E	X4	N	X4
L	X24	F	X8
O	X8		

L X24
DIA3x14mm


F X8
DIA4x20mm

O X8


STEP 3




STEP 4



STEP 5




STEP 6





C	X2
 DIA8x30mm	
D	X2
 DIA3x30mm	

STEP 7




C	X4
 DIA8x30mm	
D	X4
 DIA3x30mm	

STEP 8




B	X8
	
T	X8
 DIA15mm	
C	X8
 DIA8x30mm	


STEP 9





STEP 10



STEP 11




STEP 12




B	X6
C	X6
DIA8x30mm	
T	X6
DIA15mm	

STEP 13








L	X8
 DIA3x14mm	
S	X8
	






STEP 14



STEP 15



STEP 16




V

V

V

V	X4
	

P	X1
	
DIA3x50mm	

Q	X1
	