







No	Name of Hardware	Fig	Q.ty	A	B
1	Washer steel		8		
2	Bolt M6x55		8		
3	Allen Key		1		
				1x	4x


Step 1:Step 2:

A




1x

B




1x

C




2x


Step 1:




Step 2:




Step 3:



Step 4:




A




1x

B




1x

C




1x


Step 1:



Step 2:



Step 3:



Step 4:

