





PARTS


①



M6x15mm

x16


②



M6x30mm

x32


③



M6x40mm

x9

④



M6x55mm

x2


⑤



M6x16x1mm


x51

⑥




M4x75x28mm


x2




Ⓐ x1




Ⓑ x1




Ⓒ x2




Ⓓ x1




Ⓘ x1




Ⓔ x1




Ⓙ x1




Ⓛ x1




Ⓚ x1




Ⓜ x2




Ⓝ x1



Ⓞ x1



Ⓟ x2




Ⓠ x1



Ⓡ x2




Ⓢ x2



Ⓣ x2

Step 1


- | | |
|---|----|
| ② | x4 |
| ⑤ | x4 |



50%

Step 2


- | | |
|---|----|
| ② | x8 |
| ⑤ | x8 |



50%


Step 3

- | | |
|---|----|
| ③ | x8 |
| ⑤ | x8 |



Step 4



- | | |
|---|-----|
| ② | x16 |
| ⑤ | x16 |



Step 5

② x2

⑤ x2





Step 6

② x2

③ x1

④ x2



⑤ x5



Step 7

① x4



⑤ x4



Step 8



① x4

⑤ x4





Step 9



- | | |
|---|----|
| ① | x8 |
| ⑤ | x8 |





Step 10






Step 11



Step 12



Step 13



Step 14

