




ASSEMBLY INSTRUCTIONS




A x1



B x1




C x1




D x16




E x1




F x1




G x1




H x2




I x1




J x1




K x1




L x1




M x1




N x1




O x2




P x2




Q x2



R x2




1 x18




M6 x 40

2 x48




M6 x 20

3 x16




M6 x 35

4 x4





M6 x 20



5 x2




1




2



3




4




5

80%




6

80%




7

80%



8



80%



9



x2

80%




10

80%




11

80%




12

80%



13

80%



14

100%

