









INSTRUCTION SHEET

04290019/01




 A × 2	 6*35mm B × 8	 15*12mm C × 8	 D × 28	 6*30mm E × 16	 5*45mm F × 8	 G × 4	 4*14mm H × 32	 I × 4
 J × 4	 K × 4	 3*11mm L × 8	 4*16mm M × 6	 6*11mm N × 6	 O × 8	 P × 12	 3*14mm Q × 12	

A








B



Step1

B




Ax2






Dx4




Step2




Step3






Step4






Step5




Step6



Step7





Step8



0x8

Step9
x2





Jx4



Kx4









Lx8



Ix4







Step10

A





Step10

B



Step11





Px12



Qx12

Step12




Px12



Qx12

Step13



10kg

10kg

10kg

