












F/80/2A

2db
724x330x16mm


Nepravilno vzmetenje lahko povzroči, da se zgornja omara odtrga. Če niste prepričani glede vrste moznika, se posvetujte s svojim prodajalcem. Na vse načine uporabite moznike, da prenesete nosilnost vzmetenja.

Nepravilna ovjes može dovesti do odkidanja gornjeg ormarića. Ako niste sigurni u vrstu tiple, obratite se svom dobavljaču. Upotrijebite tiple na svaki način da poduprete ovjes.


O suspensie necorespunzătoare poate duce la ruperea dulapului superior. Dacă nu sunteți sigur cu privire la tipul de diblu, consultați distribuitorul. Folosiți dibluri în toate modurile pentru a rezista la capacitatea de încărcare a suspensiei.

AK 103
2 XPL 16
2 XHK 01
2 XFT 13
2 XPN 02
2 XFR 12
2 XKO 01 8*30
18 XKN 03 7*50
12 XPL 12
12 XKL 01 4 mm
1 XPN 01
2 XPD 01
2 XUC 11 (128 mm)
2 XDR 27 3,5*16
16 XDR 25 4*25
2 XKV 01 1,5*20
30 XUC 06
2 XDR 42 4*30
4 X


1.




2.




4.




5.





6.




7.





9.



10.

