









INSTRUCTION SHEET

04290026/06





 6*35mm Ax17	 15*12mm Bx9	 Cx2	 6*30mm Dx20	 4*25mm Ex4	 4*30mm Fx18	 3.5*12mm Gx24	 φ20mm Hx17	 4*40mm Ix9
 Jx5	 4*14mm Kx20	 Lx1	 φ20mm Mx4	 Nx2	 Ox2	 Px2	 Qx2	 15*10mm Rx8


Step1





Step2




Step3



Step4




Step5




6*30mm
Dx6


4*40mm
Ix9

Step6




4*30mm
Fx10



φ20mm
Mx4


Jx5



4*14mm
Kx20


Lx1


Step7



Step8



Step9



Step10

