



25130008/01








2PER



30 MIN


PART LIST



HARDWARE LIST

A

X28



B

X28



C

X28












D

X26




DIA8x40mm


STEP 1






STEP 2






STEP 3








STEP 4








STEP 5




STEP 6



STEP 7



STEP 8



STEP 9

