




INSTRUCTION SHEET


04290026/07




x2




① x1




② x1




③ x1




④ x1



⑤ x1



⑥ x2




⑦ x1



⑧ x1



⑨ x4




⑩ x3




⑪ x3




⑫ x3



⑬ x3



⑭ x3



⑮ x1



⑯ x2



6*35mm
Ax24



15*12mm
Bx12



15*10mm
Cx12



6*30mm
Dx12



4*25mm
Ex8



4*30mm
Fx22



Gx4



Hx2



Ix2



φ20mm
Jx24



3*14mm
Kx12



3*12mm
Lx2



Mx12



Nx2



4*14mm
Ox12



5*25mm
Px4



6*30mm
Qx2



Rx5



4*14mm
Sx20



Tx1



φ20mm
Ux4



Vx3



Wx3



Xx3



Yx3




3.5*12mm
Zx36




4*45mm
AAx2


Step1




Step2




Step3





Step4



Step5




Step6




 φ20mm Jx6	 15*12mm Bx6	 6*30mm Dx6
---	---	--

Step7




- Ix2
- 4*25mm
Ex2
- 3*12mm
Lx2
- Gx1
- 4*14mm
Ox4
- Nx2

Step8




- Ax12
- 4*30mm
Fx12
- 15*10mm
Cx12
- Ø20mm
Jx12
- 4*25mm
Ex6
- Gx3


Step9



Step10




Step11




5*25mm
Px4

Step12




4*14mm
0x8

Step13



Step14



6*30mm
Qx2



4*45mm
AAx2

