








INSTRUCTION SHEET



25820007-02





				
ax8	bx8	cx16	dx7 Ø4x40	ex8 Ø6x45
				
fx8	gx8	hx4	ix24 Ø4x14	kx12 Ø3x14
				
lx1	mx1	nx2	ox2 Ø3x12	px8
				
				qx4

1



ax4



cx16





jx2








kx4


2





3




4



5



6




kx8



px8

7



hx4



ix8




nx2



ox2

8



ix16




mx1




dx1


step1




step2




step3



step4



step5



9

