





PARTS


①



M6x15mm

x16


②



M6x30mm

x32


③



M6x40mm

x9

④



M6x55mm

x2


⑤



M6x16x1mm


x51

⑥




M4x75x28mm


x2




Ⓐ x1




Ⓑ x1




Ⓒ x2




Ⓓ x1




Ⓘ x1




Ⓔ x1




Ⓙ x1




Ⓛ x1




ⓖ x1




ⓓ x2




Ⓚ x1



Ⓛ x1




Ⓜ x2




Ⓞ x1



Ⓤ x2




Ⓩ x2



ⓧ x2



Step 1

- | | |
|---|----|
| ② | x4 |
| ⑤ | x4 |




Step 2

- | | |
|---|----|
| ② | x8 |
| ⑤ | x8 |



Step 3


- | | |
|---|----|
| ③ | x8 |
| ⑤ | x8 |



50%

Step 4



- | | |
|---|-----|
| ② | x16 |
| ⑤ | x16 |



50%



Step 5

- | | |
|---|----|
| ② | x2 |
| ⑤ | x2 |



Step 6



- | | |
|---|----|
| ② | x2 |
| ③ | x1 |
| ④ | x2 |
| ⑤ | x5 |



Step 7

① x4



⑤ x4



Step 8



① x4

⑤ x4





Step 9



- | | |
|---|----|
| ① | x8 |
| ⑤ | x8 |





Step 10






Step 11



Step 12



Step 13



Step 14

