







ASSEMBLY INSTRUCTION


11970005/01



HARDWARE

Ref	Product name	Qty
1	 M6x40mm	8
2	 M6x25mm	2
3	 Ø6/16mm	10
4	 M4	1
A	 F	2
B	 F	2
C	 F	1
D		1
E		1
F		2


STEP 1




ASSEMBLY INSTRUCTION

11970005/01






STEP 2




ASSEMBLY INSTRUCTION
11970005/01



HARDWARE

Ref	Product name	Qty
1	 M6x40mm	8
2	 6Øx16mm	8
3	 M4	1
A		2
B		2
C		1
D		1
E		1


STEP 1



ASSEMBLY INSTRUCTION

11970005/01


STEP 2




ASSEMBLY INSTRUCTION

11970005/01

A = 1x



B = 4x




1 = 8x




M6x40mm

2 = 8x





Ø6/16mm

3 = 1x




M4

STEP 1




STEP 2




ASSEMBLY INSTRUCTION

11970005/01

A = 1x



B = 4x




1 = 8x




M6x40mm

2 = 8x





Ø6/16mm

3 = 1x



M4

STEP 1



STEP 2

