










04890065-01/02

SURI


BDSK Handels GmbH & Co. KG  
Mergentheimer Straße 59  
DE-97084 Würzburg  
Germany






<b>Ax1</b> 	<b>Bx1</b> 	<b>Cx1</b> 	<b>Dx8</b> M6x20 
<b>Ex8</b> φ6x18x1.5 	<b>Fx1</b> 5# 	<b>Gx1</b> 4# 	





# 1




Dx4	Ex4	Fx1
M6x20	φ6x18x1.5	5#
		


# 2






Gx1
4#






# 3



Dx4	Ex4	Fx1
M6x20	$\phi 6 \times 18 \times 1.5$	5#
		

# 4



5

