



PROFI PFS01





a1 8x35 x....(x12)	b0 x....(x8)	b3 x....(x8)
c1 Euro 4x13 x....(x16)	d6 x....(x16)	e0 x....(x8)
e1 x....(x8)	f1 x....(x2)	g0 x....(x4)
g2 7x60 x....(x4)	i2 4x16 x....(x1)	i4 3,5x27 x....(x6)
i11 4x30 x....(x8)	h1 x....(x2)	
j1 3x20 x....(x4)	m x....(x1)	n2 3,5x16 x....(x8)
o13 x....(x4)	q9 x....(x1)	
r4 x....(x12)	u5 x....(x1)	u6 x....(x2)
u7 x....(x2)	z x....(x1)	


- ① - C2
 - ② - C2
 - ③ - C1
 - ④ - C1
 - ⑤ - C1
 - ⑥ - C1
 - ⑦ - C3
 - ⑧ - C3
 - ⑨ - C3
- C1

C2








C3









- 90 min.









2






3



4
▼



5
▼



6

