








**ACE**




|            |            |            |            |        |
|------------|------------|------------|------------|--------|
|            |            |            |            |        |
| A x 4      | B x 4      | C x 1      | D x 1      | E x 1  |
|            |            |            |            |        |
| F x 12     | G x 12     | H x 2      | I x 4      | J x 28 |
|            |            |            |            |        |
| K x 1      | L x 4      | M x 2      | N x 4      | O x 2  |
|            |            |            |            |        |
| P x 1      | R x 8      |            |            |        |
|            |            |            |            |        |
| 1 x 1 (C1) | 2 x 1 (C1) | 3 x 1 (C1) | 4 x 3 (C1) |        |
|            |            |            |            |        |
| 5 x 1 (C2) | 6 x 2 (C3) | 7 x 1 (C3) |            |        |



1




2




4x45  
Gx6

5



3



4




5



4x16  
Rx8


6

x8




7


7



8



9






M8x20  
Jx4

8

10



x2



M8x20  
Jx2




4x45  
Gx4




Hx2


11



x2




4x45  
Gx2




Hx1




12



13




14





Ex1




M8x16



Mx2

15


x2



Ox2

16

Ox2



17

