







INSTRUCTION SHEET


04290025/05





Step 1








Step 2




Step 3



Step 4



Step 5



- | | | | | | | | |
|---|---|---|---|---|---|---|---|
|  I x 1 |  K x 1 |  M x 1 |  N x 1 |  C x 4 |  E x 4 |  L x 6 |  A x 4 |
|---|---|---|---|---|---|---|---|

Step 6

