



Pan


TYP 1



TYP 3



TYP 2



№	L	B	T	st.	pack.
1	1650	100	25	1	1
2	1650	100	25	1	1
3	1650	100	25	1	1
4	1650	100	25	1	1
5	2000	100	55	2	1
6	2000	100	55	1	1
7	2000	100	55	1	1
8	2000	100	25	2	1
9	700	100	25	4	2
10	1000	100	25	4	2
11	1000	100	25	8	2
12	1421	100	25	1	2
13	1421	100	25	1	2
14	450	90	25	4	2
15	450	100	25	2	2
16	450	100	25	2	2

--DE--

Sehr geehrter Kunde!

Es können Staubrückstände auf den Oberflächen sein, bitte entfernen sie es mit ein feuchten Baumwolltuch.

--CZ--

Vážený zákazník!

Tam může být usazování prachu na povrchu, odstraňte vlhkým bavlněným hadříkem.

--SK--

Váženy zákazník!

Tam môže byť usadzovanie prachu na povrchu, odstráňte vlhkou bavlnenou handričkou.

--HR--

Poštovani kupci!

Tu može biti naslage pražine na površini, uklonite ga vlažnom pamučnom tkaninom.

--HU--

Tisztelt Ügyfelünk!

Lehet, hogy a por lerakódások a felszínen, kérjük, törölje le egy nedves pamut ronggyal.

--SL--

Spoštovani kupec!

Obstajajo lahko prah na površini z vlažno bombažno krpo odstranjeni.

--Se--

Kära kunder,


Det kan finnas damm avsättning på ytan, torka av med en fuktad bomullstrasa.

--EN--


Dear customer!

There may be dust residues on the surfaces, please remove it with a damp cotton cloth.

A*48



B*112



C*28



M6*45

D*2




E*28



M6

F*12



7*50

G*12



d8

H*4





d5



L*12




d10




110 min






1





B*112




2



3



4




C*12

E*12




M6*45



M6

5



A*16

6,3*70

C*6


E*6



M6*45




M6




6

TYP 2


TYP 1



TYP 3



F*4



C*10



M6*45

E*10




M6


7

TYP 2

TYP 1



TYP 3



G

L

L*12 G*12

H*4



d10



d8



d5