



90 min

USK 60 2A

00020010-10



±8x30mm	6,4 x 50mm	±6x42mm	±12/10mm
A	B	B2	C5
16	8	8	4


L=20mm			6.5x48x16	L=450mm	l11	L	±6.3x13mm		±4.0x45mm	±3.5x13mm
D2	E1	E9	F2	L	l11	L	M2	O	P4	P5
4	8	2	4	2	4	4	16	1	2	12

±3.0x20mm	±3.0x16mm	±4.0x25mm			8x20x100mm	M4x27mm
P7	P11	R	S	T15	T14	U8
4	10	2	2	6	2	4


ISM-KUH-01249



KUH.60295




KUH.20002




KUH.10346

KUH.90011


KUH.60001




KUH.90012




KUH.90011



KUH.90010




KUH.90015



KUH.10345

KUH.70810



WST.0145

WST.0109

KUH.60295

WST.0110

KUH.70809

x2





KUH.10345	815x550x16
KUH.10346	815x550x16
KUH.20002	600x600x16
KUH.60001	585x585x2,5
KUH.60295 x2	537x448x2,5
KUH.70809 x2	286x596x19
KUH.70810	133x596x19
KUH.90010	567x100x16
KUH.90011 x2	567x100x16
KUH.90012	567x130x16
KUH.90015	599x95x16
WST.0109 x2	450x140x12
WST.0110 x2	450x140x12
WST.0145 x2	527x140x12



1



$\pm 12/10\text{mm}$  C5 4	$\pm 8 \times 30\text{mm}$  A 8
--	---

x2






2

$\pm 6 \times 42\text{mm}$  B2 8




x2








3










$L=20\text{mm}$  D2 4
--







x2
















4





5









6.5x48x16 F2 4	±8x30mm A 8	L L=450mm I11 2	±6.3x13mm M2 16	±3.5x13mm P5 6	T15 6
----------------------	-------------------	--------------------------	-----------------------	----------------------	----------







7

6,4 x 50mm		
		
B	O	E1
2	1	2




8



6,4 x 50mm		
		
B	O	E1
2	1	2


9

6,4 x 50mm



B

4









O

1




E1

4







10



11

3.0x16mm




 P11
 10









12


4.0x25mm

 R
 2




3.5x13mm	4.0x45mm	
		
P5	P4	E9
6	2	2







1.



2.



3.




	M4x27mm	3.0x20mm
		
S	U8	P7
2	4	4

8x20x100mm





T14


2





T14




T14



T14



4.0x27mm



x2

4.0x27mm

