













1.

M1 490_1 4


rauch



2.




3.



M1490

4.



M1490

[illegible]

3

18

Bo2


10mm

Diagram illustrating the assembly of a screw (233) into a bracket (Se1) attached to a base (Bo1). The screw is shown being inserted into the bracket, which is mounted on the base.


M1490

7.

5 1 779




6 1 779




M1490

8.

7 1 779




8 1 779




M1490

9.

9 807




10 233




M1490

10.

11 1 233 779




12 296




M1490

11.

13 554 656 926 927




14 31 32




12.

15 211 580 938





16

201





13.





M1490

14.





M1490

15.






M1490







16.






M1490




25 876




27




28




29




30




31 271



21.




33 **45**



M1490

22.

34 **144**



M1490