

CAUTION: Because of the edges of some parts before assembly may be sharp, please handle unassembled parts carefully



Parts list	Qty
A	1
В	2
C	1
D ► M6*10MM	4
E ← M6*20MM	4
F M6*35MM	2
G	1



Attach the leg B with screws F,then C with screws D as show.



Attach the leg B with screws \boldsymbol{E} as show.



Attention:

Be careful when you install the product. Inspect the screw to insure the product in good condition after several months. Dont shake it violently, safely use keeps you safe.