








U 100 ZAP




+8x30mm	6,4 x 50mm	+6x42mm			6.5x48x16	+35/0mm
A	B	B2	E1	E9	F2	HG
20	10	4	8	2	4	4
L=450mm	+5/19mm	L1=680mm	+5.0x13mm		0,05	+4.0x45mm
I5	J	L1	M	O	O11	P4
2	4	1	12	1	1	2
+3.5x13mm	+3.0x20mm	+4.0x35mm	+4.0x30mm			
P5	P7	P24	R2	S30		
20	15-20	4	8	4		




ISM-KUH-01042


1



2














3




4

6.5x48x16 F2	∅8x30mm A	∅35/0mm HG	∅3.5x13mm P5	L=450mm I5	∅5.0x13mm M
4	8	4	8	1	6




5

6,4 x 50mm



B

4





O

1




E1

4




E1



B


6

6,4 x 50mm



B

4




O

1




E1

4





E1




B

7

L=450mm  I5 1	±5.0x13mm  M 6	6,4 x 50mm  B 2	 O 1
--	---	--	--





KUH.90025



8

L1=680mm  L1 1
--



KUH.60022

KUH.60022





9

+3.0x20mm



P7

15-20



10

+4.0x45mm






P4

2



E9

2




11

±5/19mm




J

4



KUH.30013




12

±4.0x35mm



P24

4




KUH.20006

P24

13

L=450mm



I5


1

±3.5x13mm





P5








12





x2




+4.0x30mm	
	
R2	S30
8	4






KUH.70021






KUH.70021








BAS 100/115 Z




max.
5kg

KUH.30005
KUH.40011
KUH.40013













A 18	B 12	C 2	D2 2	E 2	E1 12	HG 4
J 4	L2 7	O 1	P5 8	P11 20-25	R2 4	S30 2



ISM-KUH-00914


1

±8x30mm	±35/0mm	±3.5x13mm
		
A	HG	P5
14	4	8




2

6,4 x 50mm



B

6







O

1




E1

6




3

6,4 x 50mm



B

6






O

1






E1


6






4



5

	$\varnothing 3.0 \times 16\text{mm}$
L2	P11
7	20-25





6

+5/19mm






J

4



7



8

4.0x30mm






R2

4







S30

2




KUH.70021




9

±15/12mm



C

2



10

±8x30mm

L=20mm



A

4



D2

2

