








2













60'













N	dim,mm			Q	P
1	801	380	18	1	1
2	801	380	18	1	1
3/3A	861	385	18	4	1
4	765	60	18	1	1
5	775	200	18	1	1
6/6A	1939	380	18	2	1
7	765	361	18	1	1
8	763	315	18	2	1
9	870	388	4	2	1
10	1073	388	4	2	1
11	725	120	16	1	1
12	737	296	4	1	1
13/13A	300	120	16	2	1
14	765	50	18	1	1


(A) Ø8x35 12	(B) 18	(C) 18	(D) 8	(E) 8	(F) Ø6.3X13 16	(P) 4	(W) 2	(V) 2
(I) Ø3.5x16 86	(J) 8	(K) 36	(X) 2	(G) 2	(L) 4	(N) 5	(H) Ø4x30 8	













(A)  $\varnothing 8 \times 35$ 2	(B)  4	(C)  4	(H)  $\varnothing 4 \times 30$ 4	(I)  $\varnothing 3.5 \times 16$ 14	(D)  4	(N)  1
---	--	--	--	---	---	--





(K)  36	(I)  Ø3.5x16 40	(X)  2	(W)  2	(V)  2
--	---	--	--	--

