




PALMA









195 cm





















72h






60 min




		 L	 R	 #10
A x 4	B x 4	C x 1	D x 1	E x 1
 3,5x30	 4x45		 M6	 M8x20
F x 12	G x 12	H x 2	I x 4	J x 30
 #5	 Ø 30			
K x 1	L x 4	M x 2	N x 4	O x 2
	 4x16			
P x 1	R x 8			






1/5




Article number	PSC	Package
1	x1	1/5
2	x1	1/5
3	x1	1/5
4	x3	1/5
5	x1	2/5
6	x1	3/5
7	x1	4/5
8	x2	5/5
9	x1	5/5










4x16
Rx8




1.




2.





3.





4x45
Gx4


Hx2





x2


4x45
Gx2

Hx1






1.




2.






Ix4



ⓐ screw all bolts 100%



0x2



8

8

