





# INSTRUCTION SHEET

04290029/01



**x 2**




E x 2

F x 2

G x 2

H x 2







I x 2



J x 2

K x 2

L x 1



**a x 32**

**b x 32**

**c x 12**



**d x 4**

**e x 16**

**f x 20**

**g x 2**

**h x 2**


**1****2**

a x 8

b x 4

Φ6x25  
c x 4Φ4x35  
d x 4


f x 4

**3**


b x 4

20kg


20kg



**4** x2



**5** x2




a x 16

b x 8

c x 4

f x 4

**6** x2







b x 8

c x 4

f x 4

**x2**

**30kg**

**7****8****9****b x 4****f x 4**